

The following is a sketch of the ZIM plant at Kuybyshev. Distances between the shops have been estimated. The corridor running through the long main building connected shops which contained large machine tools, lathes, and drills. The long structure housed more than half of the plant's production activity, including a foundry, a metal stamping and pressing shop, and a milling shop for small metal work.

